

## Job Description Cartoner

### SUMMARY

Responsible for placing finished product trays into display boxes and placing display boxes into corrugated shippers. If absent, another trained employee or trained backup will be scheduled to cover responsibilities for this position.

### PRIMARY RESPONSIBILITIES

1. **Personal Protective Equipment Required (PPE):** ear plugs, hairnet, required gloves, clean smock, and assigned footwear. Comply with product contact GMPs (QA0183WI Good Manufacturing Practices).
2. Visually check for correct card placement and code date on trays.
3. Place the appropriate amount of finished product trays into the correct display box.
4. Lift flat corrugated shippers onto the table as needed.
5. Assemble display boxes as needed.
6. Place display box into a corrugated shipper if needed.
7. Place finished box on the conveyor.
8. Adhere to company employee hygiene practices, company food safety procedures and GMPs.
9. Other duties as assigned by the Lead and Production Supervisor.

### PHYSICAL ENVIRONMENT/WORKING CONDITIONS

This position is in a manufacturing environment and will involve standing for long periods of time, working in temperatures less than 50 Degrees Fahrenheit, repetitive hand movements, and occasional lifting of up to 10 lbs. May be required to work an occasional Saturday and/or Sunday as needed.

### EQUIPMENT AND MACHINERY USED




Conveyor

### TRAINING REQUIREMENTS

New Employee Orientation and on the job training.

### SIGNATURES

Signatures below constitute employee's understanding of the responsibilities and requirements of the position and Supervisor's verification that the employee is competent to complete the required tasks.

 <hr style="border: 0; border-top: 1px solid black; margin: 0;"/> Employee Printed Name	 <hr style="border: 0; border-top: 1px solid black; margin: 0;"/> Employee Signature	Date <u>02/21/22</u>
 <hr style="border: 0; border-top: 1px solid black; margin: 0;"/> Supervisor Signature		