



S.R.C. - Pipestone, MN U.S.A.

# Suzlon Accident Report

Team Member: Cynthia Ferrera

Taken to Hospital or Clinic? Y\_\_ N

Date of Occurrence: 2-12-08

Is This a Near Miss? Y\_\_ N\_\_

Time of Occurrence: 6:30 PM

Date Reported: 2-12-08

Team Leader: Mike Kellen

Department: Mould

Day shift \_\_ Night shift

Location of where accident occurred (be specific)

Main Mould Blue Line

Description of accident / injury

Was Exposed to Resin & Fiber Glass and a rash broke out on her Arm's

Witnesses names

Corrective action (If needs further investigation use form F:ST:02)

Was told to go and see her doctor.

Employee Feedback

Cynthia J Ferrera

Team Member Signature

2-12-08

Date

Mike Kellen

Team Leader Signature

2-12-08

Date

Safety Officer Signature

Date

Team Leader: Perform Accident Investigation, Implement Corrective Action, and submit completed form to the Safety and Environmental Officer before the end of your shift.

**RECEIVED**  
FEB 22 2008